

## CONNECTING BATTERIES BEFORE USE

Low = 16 Hrs



1x - 3 sec

Medium = 8 Hrs




2x - 3 sec

High = 4 Hrs




3x - 3 sec




1x - 5 sec

## TURNING ON

## TURNING OFF



## HOW TO CHARGE →



## REMOVE BATTERIES BEFORE HEAT MOLDING